

Date: Wednesday, 07/05/2008 1:10:08 PM
 User: Julie Lecocq

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.		Drawing Name	: D3552-11		
Job Number	: 39107		Part Number	: D355211		
Estimate Number	: 10804		Drawing Number	: R08-045/NCR08-037		
P.O. Number	:		Project Number	:		
This Issue	: 07/05/2008	S.O. No. :	Drawing Revision	:		
Prsht Rev.	: NC		Material	:		
First Issue	: 07/05/2008	Type	: PURCHASED PARTS		Due Date	: 14/05/2008
Previous Run	: 00015		Qty:	1	Um:	Each
Written By	:					
Checked & Approved By	: <u>JUL 08.5.07</u>					
Comment	:					

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	D355211	Gas Spring
Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s) Gas Spring original B33533		
2.0	QC5	INSPECT WORK TO CURRENT STEP
		<i>08.05.07</i>
Comment: INSPECT WORK TO CURRENT STEP Scrap and destroy strut. See NCR08-037 for more details.		
3.0	QC21	FINAL INSPECTION/W/O RELEASE
		<i>08/06/19</i>
Comment: FINAL INSPECTION/W/O RELEASE		

Job Completion

*MF 08-06-16*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries